

TEMPO MARKER temporary marking spray paint



Product codes:

Reference: 141719

EAN13: -

UPC: -

Product attributes:

Color: Orange, Blue, Cherry

Volume: 500 ml

Product features:

Product Type: Temporary Marking Spray

Type of paint: Fluorescent paint

Marking time: 1 month

Volume: 500 ml

Packaging: Box of 12 aerosols

Brand: SOPPEC

Product short description:

TEMPO MARKER paint is the ideal aerosol for short-lived ground markings. Especially suitable for very short-term markings, this temporary marking paint is useful for signalling and marking out sports (races, hikes) and other events (car boot sales, markets, shows and leisure events).

Product description:

TEMPO MARKER : THE TEMPORARY MARKING SPRAY PAINT FOR VERY SHORTTERM MARKING

Properties of the TEMPO MARKER temporary marking spray paint

Can be used on many different surfaces: concrete, grass, wood and asphalt.
A particularly robust safety cap (no rupture if a full aerosol is dropped from a height of 1.50m).

- Highly fluorescent, visible from a distance.
- Marking duration: from a few days to 1 month maximum
- Rapid drying: approximately 10 min.
- Temperature range: -20 to 50°C
- Natural elimination of the colour completed by mechanical action (water jet, low pressure cleaner, brushing, etc).

Specifications of the TEMPO MARKER temporary marking paint

Composition

Binder: acrylic.

Pigments: mineral and organic specifically selected to facilitate rapid degradation due to UV exposure.

Solvents: complex blend free from chlorinated solvents and aromatic compounds.

Propellant: specific blend of isobutane and propane.

Application method

Manually or using our marking accessories (Marking rod & Marking paint hand gun).

Before use: shake vigorously head down.

After use: purge head up.

Health and safety

Safety data sheets are available free of charge on the internet: www.quick-fds.com.

No paint mist or drips during use.

CLP labelling with two pictograms.

DANGER

H222 Extremely flammable aerosol.
H229 Pressurised container: May burst if heated.
H319 Causes serious eye irritation.
H336 May cause drowsiness or dizziness.

Safety Data Sheet

GET THE SAFETY DATASHEET